



RIVA RACING
PERFORMANCE PRODUCTS & ACCESSORIES

Yamaha Billet Driveline Coupler Kit

RY30040-BDC



Applications:

Yamaha 1.8/1.9L Engines

Approximate Installation Time:

5.5 hours

* Installation Note:

Torque supplied billet holder cap to 15 ft•lb (20.3 N•m) maximum.

Required Specialty Tools:

Yamaha OEM Service Manual
Yamaha Coupler Tool
Yamaha Crankshaft Holder
Yamaha Shaft Holder
RIVA Driveline Coupler Tool
or Kawasaki Coupler Tool

Part

Please call
[80-412H](#) or 90890-06729 or YW-06729
[YW-06562](#) or 90890-06732
[35-06730](#) or 90890-06730 or YW-06730
[RY30040-DCT](#)
[20-3310](#) or 57001-1423

Recommended Specialty Tools:

1/2" or 3/4" Breaker Bar & Impact Gun
Heat Gun
Heavy-duty Industrial Bench Vise

Part

N/A
N/A
N/A

Required Materials:

Loctite 648
Loctite 572

Part

N/A
N/A

Installation should be performed only by a qualified and/or experienced mechanic following the guidelines outlined in the Yamaha OEM Service Manual*. Failure to properly install these couplers falls solely on the end user. Due to the nature of performance applications these couplers are sold without any express warranty or any implied warranty of merchantability or fitness for a particular purpose. RIVA Racing shall not, under any circumstances, be liable for any special, incidental or consequential damages, including, but not limited to damage, or loss of profits or revenue, cost of purchased or replacement goods, or claims of customers of the purchaser, which may arise and/or result from sale, installation or use of these couplers. Installation could adversely affect the vehicle manufacturer's warranty coverage.

Technical Support

For answers to questions regarding installation or trouble shooting RIVA Performance Products contact:

RIVA Technical Support directly at (954) 247-0705 or by e-mail at tech_support@rivaracing.com.